UNCLASSIFIED

AD NUMBER AD021026 CLASSIFICATION CHANGES TO: unclassified FROM: confidential LIMITATION CHANGES

TO:

Approved for public release; distribution is unlimited.

FROM:

Distribution authorized to U.S. Gov't. agencies and their contractors;

Administrative/Operational Use; OCT 1953. Other requests shall be referred to Naval Proving Ground, Dahlgren, VA.

AUTHORITY

USNSWC ltr, 17 Nov 1977; USNSWC ltr, 17 Nov 1977

U. S. NAVAL PROVING GROUND DAHLGREN, VIRGINIA

REPORT NO. 1180

WEAPON "A" LAUNCHER CHANGES

ROCKET LAUNCHER MARK 19 MOD 0 PROOF FIRING TEST OF PRODUCTION MODEL

FINAL Report

Assignment NPG-Re5e-88-2-53

Copy No. ____

Classification CONFIDENTIAL SECURITY INFORMATION

This document has been reviewed in accordance with OPNAV iNST 5610.17. The security classification arrighed hereto is correct. The title of the discussion is unclassified; the abstract of Confidential.

PART A

SYNOPSIS

- 1. a. The Rocket Launcher Mark 19 Mod 0 is a sub-caliber launcher for the Anti-Submarine Rocket Launcher Mark 108. It is capable of firing, in sequence, six 4"0 sub-caliber rockets. The prototype launcher was previously test fired at the Naval Proving Ground.
- b. Ballistic data had been recorded on the experimental 4.0 Sub-Caliber Rockets during firing tests of the prototype Eocket Launcher Mark 19 Mod 0 and firings conducted from an open rail type launcher. The rounds exhibited considerable yaw in flight and excessive dispersion. The Bureau of Ordnance requested that ballistic data be recorded during the present test.
- 2. This test was conducted to:
- a. Proof test fire the production model of the Rocket Launcher Mark 19 Mod 0.
- b. Collect additional ballistic data for ballistic evaluation of the experimental 4.0 Sub-Caliber Rockets.
- 3. It is concluded that:
- a. When the Rocket Launcher Mark 19 Mod 0 is leaded in the Rocket Launcher Mark 108:
- (1) Between -30° and +30° in train only one of the two Mark 108 firing pins is operative and any two adjacent rockets of a salvo can fire simultaneously.
- (2) With the mount trained 35° off the centerline, both Mark 108 firing pins are operative, and the rockets will fire individually in the proper sequence.
- b. The experimental 4.0 Sub-Caliber Rockets exhibit excessive yaw during burning and the dispersion is greater than is desirable.

4. It is recommended that:

- a. The Rocket Launcher Mark 108 be trained 35° off the centerline before loading the Rocket Launcher Mark 19 Mod 0 into the guide tube.
- b. Prior to starting a firing program the firing pins of the Mark 108 Launcher should be checked to see that they are contacting the contact band on the spacer tube of the loaded Mark 19 Launcher.
- c. The experimental 4%0 Sub-Caliber Rockets be modified to improve their flight and decrease their dispersion.

1

TABLE OF CONTENTS

Page	
SYNOPSIS	
TABLE OF CONTENTS	
AUTHORITY4	
REFERENCES	
BACKGROUND 4	
OBJECT OF TEST	
PERIOD OF TEST	
REPRESENTATIVES PRESENT	
DESCRIPTION OF ITEM UNDER TEST	
DESCRIPTION OF TEST EQUIPMENT	
PROCEDURE	
RESULTS AND DISCUSSION	
CONCLUSIONS	
RECOMMENDATIONS	
DISPOSITION OF MATERIAL	
APPENDIX A = NPG PHOTOGRAPHS	1)
APPENDIX B - TABLES OF RESULTS	1) y)
APPENDIX C - NPG SKETCH TE101	
OF OPERATION	
APPENDIX D - DISTRIBUTION	

PART B

INTRODUCTION

AUTHORITY:

This test was requested and authorized by reference (a) as modified by references (b) and (c), and conducted under Task Assignment NPG-Re5e-88-2-53 established by reference (d).

2. REFERENCES:

- a. BUORD Conf ltr Re5e-WJL:hts Ser 38750 of 5 May 1952 b. BUORD Conf ltr Re5d-KEY:jlj S79-5 (1) Ser 53396 of 12 Mar 1953
- BUORD Conf ltr Re5d-KEY: jlj S79-5 (1) Ser 54854 of 8 Apr 1953
- BUORD Conf ltr Re5e-CEA:hts NP9 Ser 42212 of 17 Jul 1952
- 0.P. 1894 (preliminary): Rocket Launcher Mark 19 Mod 0. Description and Instructions
- f. NPG Conf ltr OTR: JAN: pps All/5806-2 Ser 23090 of 11 Sep 1952
- NPG Conf ltr OTR: JAN: dmf All/5388-2 Ser 23793 of 13 Jan 1953
- NPG Conf ltr OTR: JAN: jlr All/532-9 Ser 31507 of 15 Apr 1953

BACKGROUND:

- The Rocket Launcher Mark 19 Mod 0, described in reference (e), is a sub-caliber launcher for the Anti-Submarine Rocket Launcher Mark 108. It is capable of firing, in sequence, six 400 Sub-Caliber Rockets. The prototype launcher was previously test fired at the Naval Proving Ground and reported in references (f) and (g).
- b. Ballistic data had been recorded on the experimental 440 Sub-Caliber Rockets during firing tests of the prototype Rocket Launcher Mark 19 Mod O and firings conducted from an open rail type launcher. The rounds exhibited considerable yaw in flight and excessive dispersion. The results were reported in references (f), (g) and (h). Reference (b) requested that ballistic data be recorded during the present test.

4. OBJECT OF TEST:

This test was conducted to:

a. Proof test fire the production model of the Rocket Launcher Mark 19 Mod 0.

b. Collect additional ballistic data for ballistic evaluation of the experimental 4.0 Sub-Caliber Rockets.

5. PERIOD OF TEST:

a •	Date	of Project Letter	14 July 1952
b.	Date	Necessary Material Receive	d 2 April 1953
C.	Date	Commenced Test	9 April 1953
d.	Test	Completed	5 June 1953

6. REPRESENTATIVES PRESENT:

LT R. J. Ronr	Bureau of Ordnance (Rej)
LT A. L. Waxman	Bureau of Ordnance (Re5b)
Mr. K. E. Yunker	Bureau of Ordnance (Re5c)
Mr. J. A. Burke	Naval Gun Factory (Code 700)

PART C

DETAILS OF TEST

7. DESCRIPTION OF ITEM UNDER TEST:

()

- a. The Rocket Launcher Mark 19 Mod 0 is a sub-caliber attachment designed to adapt the Rocket Launcher Mark 108 to the firing of 4.0 Sub-Caliber Rockets in anti-submarine practice. The launcher consists of two principal components, a tube assembly and a spacer assembly, as shown in Figure 1. The complete launcher assembly is inserted in the guide tube of the Rocket Launcher Mark 108. It is sub-divided to hold six (6) 4.0 sub-caliber rockets, as shown in Figure 2. The assembled round is shown in Figure 3. When properly energized, an electrical firing mechanism (Figures 2 and 4), contained in the tube assembly, fires the rockets in sequence. The operation of the firing mechanism is explained in Appendix (C). The Rocket Launcher Mark 108 operates in a normal manner with the Mark 19 Launcher inserted in the guide tube. The director controls elevation and train and the local mount operator fires the rounds.
- b. The experimental 4%0 Sub-Caliber Rockets consisted of three components:
 - (1) 440 Rocket Head NOTS Model 101-A, BUORD Sketch 338313A.
 - (2) 2"25 Rocket Motor NOTS Model 103A, Charge Mark 16 Mod 1.
 - (3) Dummy Depth Charge, BUORD Sketch 321058.

A detailed description of the Rocket Launcher Mark 19 Mod 0 and the experimental 400 Sub-Caliber Rocket is given in reference (e).

- 8. DESCRIPTION OF TEST EQUIPMENT:
 - a. Rocket Launcher Mark 108 Mod 2
 - b. Multiple Channel Recording Oscillograph.
 - c. Tray fabricated from 14 ft. length of 13 in. diameter steel pipe.
 - d. Manually operated firing board.

CONFIDENTIAL SECURITY INFORMATION

9. PROCEDURE:

The test was conducted in three phases:

a. Phase I

The Rocket Launcher Mark 19 Mod 0 was loaded with six rockets and hoisted into the Mark 108 guide tube. The guide tube was set at 0° train and elevation set as shown in Table I. Both the train and elevation power drives were operating. The firing circuit was operated in LOCAL with a 5 second interval between rounds. Seven salves were fired. The Mark 19 Launcher malfunctioned at least once during each salvo, starting with the first salvo. Two rounds fired simultaneously when the firing circuit was closed to fire a single round. The malfunction will be discussed in detail later in this report. In an effort to determine the cause of the malfunction it was necessary to modify the test procedure. After each salve the firing mechanism containing the sequential "stepper switch" was removed from the launcher tube and tested. In each case it functioned normally. On salvos 4 through 7, a recording oscillograph was employed to measure voltage and current in the firing circuit, in an effort to determine the reason for malfunctioning.

b. Phase II

It was necessary to isolate the Mark 19 Launcher from the Mark 108 Launcher in order to determine the reason why two rounds of each salvo were firing simultaneously. A trough was fabricated by cutting a 14 foot section of 13 inch diameter steel pipe in half, lengthwise. The trough was secured to a foundation at 11° elevation and the launcher secured in the trough. Figures 5 and 6 show the relation of these components. Two salvos (Numbers 8 and 9) were fired with the launcher in the trough. The firing circuit was controlled through a manually operated firing board. This completely eliminated the firing circuit of the Mark 108 launcher. Voltage and current in the firing circuit were recorded on a multiple channel recording oscillograph.

c. Phase III

The remaining salvos (Numbers 10 through 16) were fired with the Mark 19 Launcher loaded into the guide tube of the Mark 108 launcher. Control and instrumentation of the firing circuit will be discussed later in this report.

10. RESULTS AND DISCUSSION:

The ballistic performance of the 4%0 Sub-Caliber Rockets continued to be unsatisfactory during this test.

A casualty record is shown in Table I and ballistic data in Table II.

a. Phase I

The first four salvos were fired under normal conditions. The six 440 rockets were loaded in the Rocket Launcher Mark 19 Mod O. The launcher and spacer tube were hoisted into the guide tube of the Rocket Launcher Mark 108.

Salvo 1 - When the firing circuit was closed to fire round 1, rounds 1 and 2 fired together. When the firing circuit was closed for the second time there was no action. On the third, fourth, fifth and sixth closing of the firing circuit the proper rounds fired in sequence. This indicated that the stepper switch of the firing mechanism had energized two firing positions with a single closure of the firing circuit. The firing mechanism was removed from the launcher and tested. It functioned normally.

Salvo 2 - The launcher was loaded as before. Rounds 1 and 6 fired together during the first closure of the firing circuit. Rounds 2, 4, 5 and 6 fired properly in sequence. Round 3 was a misfire. It fired on the second revolution of the stepper switch (9th closing of the firing circuit). This sequence of firing indicated that the stepper switch fired round 1, stepped backward to fire round 6, and returned to the proper position to fire round 2 when the circuit was closed on the second attempt to fire. The firing mechanism was removed, tested and found to be operating satisfactorily.

Salvo 3 - The firing mechanism was set to commence firing with tube No. 3. This was done to determine whether the first two rounds would always fire together during a salvo or whether this only occurred when tube No. 1 was involved. The first five rounds fired normally. Round 6 (in tube No. 2) was a misfire. Examination showed it had moved off its firing pin. The only apparent explanation is that the round was not firmly seated and was moved forward by the gas pressure of preceding rounds.

Salvos 4 through ? - The cause of previous dual firing was believed to be a temporary surge or voltage drop in the firing circuit, causing the stepper switch to cycle. This would cause rounds to fire together with a single closing of the firing circuit The firing circuit was instrumented to measure current and voltage at the instant of firing. Dual firing occurred on salvos 4 through ? inclusive. The oscillograph records indicated that electrical instability in the firing circuit occurred concurrently with the double rounds. An explanation is provided in Appendix (C). Prior to salvo No. ? a new firing mechanism was installed that had been thoroughly tested. Dual firing recurred.

b. Phase II

Two salvos (8 and 9) were fired with the Mark 19 Launcher secured in a metal tray (described in paragraph 9b and shown in Figures 5 and 6). This was done so that the firing circuit of the Mark 108 Launcher could be completely eliminated during firing.

Salvo 8 - Only the launcher tube was used in the tray, with the spacer tube omitted as shown in Figure 5. The stepper switch was removed from the firing mechanism. Individual firing leads controlled by knife switches were run to each firing pin and a common ground was provided. Voltage in each firing lead was recorded. The salvo fired normally. Voltage reached only the firing pin for which it was intended as each individual rocket was fired. At this point it was definitely determined that the double rounds were being fired electrically as a result of faulty stepper switch action caused by a temporary power interruption at some point in the firing circuit.

Salvo 9 - This was fired with the complete launcher in the tray, the stepper switch reinstalled and the spacer tube used, as shown in Figure 6. A firing lead, from a manually operated firing board, was securely attached to the spacer tube and a positive ground return provided. The salvo fired normally. Voltage reached the individual firing pins in the proper sequence. This indicated that all elements of the complete Mark 19 Launcher were functioning properly.

c. Phase III

Salvos 10 through 16 - Six salvos were fired with the Mark 19 Launcher loaded into the guide tube of the Mark 108 Launcher as described in Phase I.

Salvo 10 - The firing circuit and power drives of the Mark 108 Launcher were not operated during this salvo. The firing circuit was controlled through the manually operated firing board described in Phase II. The salvo fired normally.

The results up to this point in the . * indicated that the Mark 19 Launcher, fired from the guide tube of the Mark 108 Launcher, functioned normally when a positive contact was provided between the source of the firing circuit and the firing lead of the spacer tube. The firing circuit of the Mark 108 Launcher is connected to two (2) firing pins in the guide tube which transmit the voltage to the contact band of the Mark 19 spacer tube. The Mark 108 Launcher is so constructed, however, that when the guide tube is loaded between -30° and +30° in train only the upper firing pin is in contact with the contact band of the spacer tube. All previous salvos fired from the Mark 108 Launcher had been loaded at 0° train. Therefore it appeared that the rocket blast and shock were partially lifting the single firing pin causing a temporary interruption of the firing circuit and allowing the stepper switch to cycle and fire two rounds simultaneously.

Salvo 11 - The Mark 108 Launcher was trained to starboard 35° off centerline during loading. This insured that both firing pins were in contact with the contact band. The salvo fired normally.

Salvo 12 was loaded on 0° train, with only one firing pin operating to verify the results. Dual firing occurred as expected.

Salvo 13 was loaded with the Mark 108 Launcher trained to port 35° off centerline. A double shot occurred. Investigation after firing disclosed that the Mark 108 Launcher was slightly out of adjustment and that only the top firing pin was operative. Consequently a momentary firing circuit break again occurred after the first round and the stepper switch cycled of its own accord.

Salvo 14 - A jumper wire was connected between the Mark 108 firing pins and the terminal lug of the Mark 19 Launcher contact band. This jumper bypassed both firing pins and provided a positive connection between the Mark 108 firing circuit and the contact band of the spacer tube. The launcher was loaded at 0° train. The salvo fired normally.

Salvo 15 was loaded 35° off centerline and fired normally.

Salvo 16 was loaded at 0° train and two rounds fired simultaneously as expected.

CONFIDENTIAL SECURITY INFORMATION

d. Dual Firing Analysis

In each case where dual firing occurred only a single firing pin was contacting the spacer tube. The dual firing encountered always occurred on rounds positioned in the same sector of the launcher tube as the firing pin. With two firing pins contacting the spacer tube one of the firing pins in the same sector as the rounds being fired may be lifted. However the other firing pin, diametrically opposite, is not affected and maintains a constant voltage supply to the firing mechanism. This assures proper functioning of the firing mechanism and fires the rounds in their proper sequence.

PART D

CONCLUSIONS

11. It is concluded that:

- a. When the Rocket Launcher Mark 19 Mod 0 is loaded in the Rocket Launcher Mark 108:
- (1) Between -30° and +30° in train only one of the two Mark 108 firing pins is operative and any two adjacent rockets of a salvo can fire simultaneously.
- (2) With the mount trained 35° off the centerline, both Mark 108 firing pins are operative, and the rockets will fire individually in the proper sequence.
- b. The experimental 400 Sub-Caliber Rockets exhibit excessive yaw during burning and the dispersion is greater than is desirable.

PART E

RECOMMENDATIONS

12. It is recommended that:

- a. The Rocket Launcher Mark 108 be trained 35° off the centerline before loading the Rocket Launcher Mark 19 Mod 0 into the guide tube.
- b. Prior to starting a firing program the firing pins of the Mark 108 Launcher should be checked to see that they are contacting the contact band on the spacer tube of the loaded Mark 19 Launcher.
- c. The experimental 400 Sub-Caliber Rockets be modified to improve their flight and decrease their dispersion.

PART F

DISPOSITION OF MATERIAL

13. The Rocket Launcher Mark 19 Mod O was retained at the Naval Proving Ground for future tests. The expended experimental 40 Sub-Caliber Rockets were scrapped.

The tests upon which this report is based were conducted by:
J. A. NEAL, Lieutenant, USN
Rocket Battery Firing Officer
Rocket Battery Division

Rocket Battery Division

Terminal Ballistics Department

This report was prepared by: J. A. NEAL, Lieutenant, USN

Rocket Battery Firing Officer Rocket Battery Division Terminal Ballistics Department

This report was reviewed by:

F. W. KASDORF, Rocket Battery Officer Rocket Battery Division

Terminal Ballistics Department

R. H. LYDDANE, Director of Research

Terminal Ballistics Department

W. B. ROBERTSON, Lieutenant Commander, USN Terminal Ballistics Officer

Terminal Ballistics Department

C. C. BRAMBLE, Director of Research, Ordnance Group

APPROVED: J. F. BYRNE

Captain, USN

Commander, Naval Proving Ground

E. A. RUCKNER

Captain, USN

Ordnance Officer

By direction

U. S. NAVAL PROVING GROUND DAHLGREN, VIRGINIA



Fourth Partial Report

on

Weapon "A" Launcher Changes

Final Report

on


Rocket Launcher Mark 19 Mod 0

Proof Firing Test of Production Model

Date:

OCT 1-1953

tube and spacer assembl



) for use with Rocket Launcher Mark iber rocket (experimental)

Mod 0 which E mechanism for Rocket Launcher Mark 19 ontains "stepper switch". LGREN, VIRGINIA S.N.P.G.



ocket Launcher Mark 19 Mod O fired from

SECURITY INFORMANT

TABLE I

CASUALTY RECORD OF ROCKET LAUNCHER MARK 19 MOD O

Nemarks	Rds. 1 & 2 fired together. Other rounds fired in sequence.	Rds. 1 & 6 fired together. Rd. 3 misfired, fired on second revolution of Stepper Switch.	First 5 rounds fired in sequence. Rd. 6 misfired. Moved off firing pinduring tiring.	Rds. 2 & 3 fired together. Other rounds fired in sequence.	Rds. 1 & 6 fired together. Other rounds fired in sequence.	Rds. 1 & 2 fired together. Rds. 5, 4, 6, fired in sequence. Rd. 5 mis-fired, fired on second revolution of Stepper Switch.	Rds. 2 & 3 fired together. Other rounds fired in sequence.
Launcher Conditions	From Mr 108 Launcher. Normal Conditions.	From Mk 108 Launcher. Normal Conditions.	From Mk 108 Launcher. Firing mechanism set to fire from Mk 19 rails in following order: 3, 4, 5, 6, 1, 2.	From Mk 108 Launcher. Normal Conditions. Current and voltage measured in firing circuit.	From Mk 108 Launcher. Normal Conditions. New firing mechanism installed. Current and voltage measured in firing circuit.	From Mk 108 Launcher. Normal Conditions. Current and voltage measured in firing circuit.	Same as Salvo 6.
Angle of Flevation Degrees	6	4	9 8	30	90	49	49
Salvo No.	H	N	10	4	io	ထ	č
Date Fired	6-7	4-9	4.9	4-21	12-7	4.28 	4-28

APPENDIX B

TARE I (Continued)

Romarks	All rounds fired normally in sequence.	All rounds fired normally in sequence.	All rounds fired normally in sequence.	All rounds fired normally in sequence.	Rds. 1 & 2 fired together. Rds. 4 & 5 fired together.
Launcher Conditions	From tray using manually operated firing board. Stepper Switch removed. Individual lead to each firing pin. Voltage measured on each firing pin. Spacer Tube of launcher not used.	From tray using manually operated firing board. Stepper Switch reinstalled. Spacer Tube used. Voltage measured on individual firing pins.	From Mk 108 Launcher using complete Mk 19 Isuncher. Manually operated firing board used bypassing individual firing pins.	From Mk 108 Launcher using complete kk 19 Launcher. Mount trained 35° off centerline during loading to allow both firing pins to contact the contact band of spacer tube.	From Mk 108 Launcher under normal conditions. Rds. 1 & 2 fired together. Loaded with Mk 108 Launcher on centerline. fired together. One firing pin in contact with contact band of spacer tube.
Angle of Elevation Degrees	נו	п	31° 20'	49	49
Salvo	α	G.	10	; #	23
Date Fired 1953	ស្	5 5	5-12	5. 2.	5-1.3

CONFIDENTIAL SECURITY INFORMATION

APPENDIX B

TAME I (Continued)

			741,5
		Remarks	Day 1 6 9 Office American Contract Contract
		Launcher Conditions	OBY South the Manager Took and the control of the c
of of	Elewation	Degrees	Ç
	Salvo	No.	t
De te	Fired	1953	ţ

6° Rds. 1 & 2 fired together. Other roums fired in sequence.	All rounds fired normally in sequence.	5° All rounds fired normally in sequences as	r- Rds. 1 & 2 fired together. Rds. 4 & 5 a- fired together.
From Mc 108 Launcher. Mount trained 35° off centerline to port to allow both firing pins to contact the contact bend. Slight misadjustment caused only one firing pin to centact the contact band of spacer tube.	From Mc 108 Launcher. Launcher firing pins bypassed by wire from Mc 108 firing circuit to contact band of spacer tube.	From Mc 108 Launcher. Mount trained 35° off centerline to allow both firing pins to contact the contact band of spacer tube.	From Mk 108 Launcher. Loaded on center- line. One firing pin contacted the con- tact band of spacer tube.
6	49	49	49
19 -	14	15	16
5-13	5-19	5-19	5-19

TABLE II

DISPERSION DATA ON 4"O SUB-CALIBER ROCKETS FIRED DURING FROOF TEST OF ROCKET LAUNCHER MARK 19 WOD O

	Lot No.	of 1953	of 1953	of 1953	. 650	670
	Rocket Mctor Lot No.	RX1049 Lot 4 of 1953	RX1049 Lot 4 of 1953	RXY1049 Lot 4 of 1953	3 Salvos Rivl049 Lot 5 of 1953	5 Selvos RIX1049
tion-Feet	Standard verage Deviation	±136	104	+125	±139	
Deflec	Average	10	69-	က္	+31	
.8-Feet	Standard age Deviation	±47	1203	1144	±105	
Reng	Average	2405	2202	2332	2647	
	Type of Round	Modified for Slow Spin	Shimmed	Unmodified	Unmodified	
to elgas	Elevation Degrees	49	30	31,0 201	67	
	No. Rds.	* 25	11 **	ejl	32	

NOES: 1. Rounds conditioned at 70°F.

2. Impacts are uncorrected for standard conditions.


3. Impacts approximately 22 ft. below trumica height.

In an effort to improve dispersion; rounds marked * were modified for slow spin by adding canted vanes in the motor nozzles, rounds marked ** were modified by wedging the depth charge inside the rocket head.

Desired dispersion should not exceed that of 12,75 Rocket which is 160 ft. in range, 422 ft. in deflection. Dispersion was excessive. S.

Rocket Motors - 2"75 Model 103A Grain Mark 16 Mod 1 (Experimental) ALN-INY. •9

CONFIDENTIAL SECURITY INFORMATION



FIRING MECHANISM FOR ROCKET LAUNCHER MARK 19 MOD 0; PRINCIPLE OF OPERATION

(Figure 7)

The firing mechanism is contained in a cylindrical tube approximately 3" in clameter and 24" long that is fitted inside the center of the Mark 19 Launcher tube at the after end. It is energized from the firing pins of the Rocket Launcher Mark 108. The six (6) firing pins of the Rocket Launcher Mark 19 are individually connected to the contacts of a "stepper switch". The "stepper switch" consists of six equally spaced contacts arranged in a circle around a wiper arm connected to the firing circuit. The wiper arm is rotated by a shaft operated by a solenoid and ratchet gear. Figure 7 shows the stepper switch set to fire round 1. When the firing circuit is closed, 20 volts AC flows through the Mark 108 firing pins to the contact band of the spacer tube (A). The spacer tube conducts the current to the firing mechanism. The current flows through the wiper arm to the No. 1 contact of the stepper switch (B), to No. 1 firing pin (C) to fire No. 1 round, and to the ground return. At the same time the current flows through a resistor and energizes solenoid (D). The solenoid attracts the armature, stretches the spring and sets up the ratchet wheel for a cycle. When the firing circuit is released by the operator the armature is released and the spring rotates the ratchet wheel (F) 1/6 of a turn moving the wiper arm to contact No. 2. When the firing circuit is closed for the second time round No. 2 is fired. Each time the firing circuit is opened and closed the cycle is repeated, firing the proper round in sequence.

At the instant of firing the firing circuit remains closed. With only one firing pin touching the contact band of the spacer tube the blast and shock lifts the pin for an instant. This interrupts the current to the solenoid causing the ratchet wheel to cycle carrying the wiper arm to the succeeding position. When the firing pin settles back in position current again flows through the stepper switch and the succeeding round is fired. Thus two adjacent rounds are fired with a single closing of the firing circuit. When both firing pins of the Mark 108 Launcher are touching the contact band of the spacer tube, at least one pin is always making contact and the firing mechanism functions properly.

DISTRIBUTION

Bureau of Ordnance			
Ad3 Re3 Re3d Re5 Re5d			1 1 1 3
Naval Gun Factory (Code 700)			2 ~
NOTS, Inyokern, California			2
Commander, Operational Developm U. S. Atlantic Fleet, U. S. Nav Norfolk 11, Virginia	ment Force val Base	• 15.5 °	· 1
Navy Research Section Library of Congress Washington 25, D. C. Via: (Re5d)			2
Local:		,	
OKB OT OTR-1 File	•		1 1 1 1